



Brake Masters #219

BAR # ARD00272208
EPA # CAL000382472
10221 Fairway Dr.
Roseville, CA 95678
(916) 774-1600
219@brakemasters.com

Invoice #2364655

Page 1 of 4
07/10/2024 4:26 PM

ALLEN PETROVICH

2001 Honda Accord
JHMCG65541C016331
Engine: 2.3L L4 (F23A1)
GAS FI
Plate: 9JFV604
Odometer In: 150801
Odometer Out: 150801

Advisor: 2961-Amilia Turner
Technician: 5861-Jesus Castillo Montes

GRAND TOTAL: \$1,247.04

✓ PAID

SERVICES

1 California Tire Pressure **SUBTOTAL: \$0.00**

WHEEL STUD BROKE DURING REMOVAL OF LEFT FRONT WHEEL. REPLACED LUGNUT AND WHEEL STUD FOR CUSTOMER.

Labor: \$0.00
Parts: \$0.00
Fees: \$0.00
Sublet: \$0.00

2 Timing Belt Replacement **SUBTOTAL: \$1,218.48**

LABOR Labor: \$850.00
REMOVE AND REPLACE TIMING BELT AND WATER PUMP Parts: \$368.48
Fees: \$0.00
Sublet: \$0.00

PARTS	PART #	QTY	EACH	TOTAL
TIMING BELT COMPONENT KIT (INCLUDES WATER PUMP)	TKH-006	1.0	\$328.48	\$328.48
BLUE EXTENDED LIFE ANTIFREEZE	252-1501	1.0	\$40.00	\$40.00
VALVE COVER GASKET SET	2000-24822	1.0	\$0.00	\$0.00

3 Courtesy Multi-Point Inspection **SUBTOTAL: \$0.00**

MAINT REQU'D LIGHT ON UPON ARRIVAL. RECOMMEND OIL AND FILTER CHANGE.

--

UNABLE TO DUPLICATE CUSTOMER BRAKE NOISE CONCERN ON TEST DRIVE. FRONT BRAKE PADS MEASURE 10MM AND REAR SHOES 3MM.

LABOR

Includes depending on vehicle: Check all dash warning lights, headlights, brake lights, turn signals, horn wipers, cabin filter. Underhood: check battery, air filter, applicable fluids, belts, master cylinder & booster, oil level, visual leaks. Undercar: tire wear, center link, pitman and idler arm, steering gear, bushings, tie rod ends, ball joints, CV axle & boots, control arms, shocks and struts, springs, sway bar bushing and links, mounts, exhaust, wheel bearings, tire pressure (CA Only), and visual leaks from oil pan A/T diff and trans case. Brakes: rotor and drum specs, brake hoses, hydraulics, brake lining specs.

4 Rotate Tires **SUBTOTAL: \$0.00**

LABOR Labor: \$0.00



Brake Masters #219

BAR # ARD00272208
EPA # CAL000382472
10221 Fairway Dr.
Roseville, CA 95678
(916) 774-1600
219@brakemasters.com

Invoice #2364655

Page 2 of 4
07/10/2024 4:26 PM

Rotate Tires

Parts: \$0.00
Fees: \$0.00
Sublet: \$0.00

5 Lug Nut / Wheel Stud Replacement

SUBTOTAL: \$0.00

PARTS	PART #	QTY	EACH	TOTAL
LUG NUT	611-138	1.0	\$0.00	\$0.00
WHEEL STUD	610-360	1.0	\$0.00	\$0.00

Labor: \$0.00
Parts: \$0.00
Fees: \$0.00
Sublet: \$0.00

Terms of Service:

For complete warranty information, please go to www.brakemasters.com/warranty/. All parts installed are new unless specifically notated. Customer authorizes the repairs and services noted on this invoice which may have been previously authorized in writing including any verbally authorized approval or revision to a prior estimate. Customer endorses the attached digital image of their signature as equivalent to their written signature as proof of their agreement and authorization. I acknowledge notice and oral approval of an increase in the original estimated price, if applicable. Customer consents to communication about this repair order via voice, text or email. This may include estimate approvals, sending of invoices or requests for feedback.

GRAND TOTAL: \$1,247.04

Total Labor: \$850.00
Total Parts: \$368.48
Total Fees: \$0.00
Total Sublets: \$0.00
Sales Tax: \$28.56

PAID

07/10/2024 04:24 PM

Paid by Credit Card via Terminal: **\$1,247.04**

CARDHOLDER/VISA xxxx-xxxx-xxxx-8013

Transaction ID: "C1i0J0OM0742scURYaP"

Signed:

Authorization:



Brake Masters #219

BAR # ARD00272208
EPA # CAL000382472
10221 Fairway Dr.
Roseville, CA 95678
(916) 774-1600
219@brakemasters.com

Invoice #2364655

Page 3 of 4
07/10/2024 4:26 PM

INSPECTION REPORT

California Tire Pressure

- Tire Pressure Right Front 32 PSI
- Tire Pressure Left Front 32 PSI
- Tire Pressure Right Rear 32 PSI
- Tire Pressure Left Rear 32 PSI
- Manufacturer Specification: 32 PSI
- Intake Form #1541172

Courtesy Multi-Point Inspection

- Air Filter
- Wiper Blades
- Battery Test



Brake Masters #219

BAR # ARD00272208
EPA # CAL000382472
10221 Fairway Dr.
Roseville, CA 95678
(916) 774-1600
219@brakemasters.com

Invoice #2364655

Page 4 of 4
07/10/2024 4:26 PM

FINDINGS

CUSTOMER REQUESTS TIMING BELT SERVICE. CUSTOMER STATES IT IS DUE TO ROUTINE MAINTENANCE. CUSTOMER ALSO REQUESTS BRAKE AND MULTI POINT INSPECTION. CUSTOMER STATES BRAKES ARE SCREECHING.

Timing Belt Replacement \$1218.48 +tax

Approved in person, 8:16am 7/9/24

Written by 2961-Amilia Turner at 07/03/2024 09:19 AM