

2-16 Positive Battery Cable Replacement

Replaced corroded positive battery cable.

Mileage: 146,545

Cost: \$76.14

Total: \$76.14



5601 PACIFIC STREET
ROCKLIN, CA 95677
(916) 624-0393
www.oreillyauto.com

Store hours:
Mon-Sat: 07:30 AM-10:00 PM
Sun: 08:00 AM-09:00 PM

Counter #: 712261 Colin
Date: 02/16/2024 05:48 PM Drawer: 9
Invoice #: 2970-149345 2970WS167

STD A32-2TB 70.99 T
BAT CABL MNT
LIMITED LIFETIME WARRANTY

1 Item

Sub-Total 70.99
Sales Tax 5.15
Total 76.14

DB 2029 9.81
DB 3391 45.80
VISA 8013 20.53

DB XXXXXXXXXXXX2029 Auth CD: 751512
REF# 477486247685

verified by PIN

DB XXXXXXXXXXXX3391 Auth CD: 946074
REF# 477489058641

Verified by PIN

VISA XXXXXXXXXXXX8013 Auth CD: 97372D
REF# 477492906089

Chip Indicator: Y
AID: A0000000031010
VISA CREDIT
TVR: 8000008000
TSI: 6800
IAD: 06011203A0A000

Warranty/Garantia:
www.oreillyauto.com/warranty